

General Environmental Incident Summary

Incident: 2038 **Date/Time Notice:** 9/11/2013 **DEM Incident No:**
Responsible Party: Bison Transport
Date Incident: 9/11/2013 **Time Incident:** 1646 **Duration:** 2 hours
County: Pembina **Twp:** 163 **Rng:** 52 **Sec:** 4 **Qtr:** NE NE NE
Lat: 48.97011 **Long:** -97.37049 **Method:** Derived from TRS
Location Description: Gas Track station off US-29 in Pembina.

Submitted By: Joshua Stebing **Affiliation:**
Address:
City: **State:** **Zip:**

Received By:

Contact Person: Bruce Smithson
1001 Sherwin Rd
Winnipeg, MB

Distance Nearest Occupied Building:

Type of Incident: Cargo Incident

Description of Released Contaminant: UN1993 Trimethyl Benzene Amines

Volume Spilled: 1.00 gallons

Ag Related: No

EPA Extremely Hazardous Substance: No

Reported to NRC: Unknown

Cause of Incident:

Loose caps on 55-gallon drums

Risk Evaluation:

of Fatalities: 0 **# of Injuries:** 0 **Affected Medium:** 01 - air

Potential Environmental Impacts:

Action Taken or Planned:

Contractor dispatched to site to secure caps of drums in tractor trailer load. Use of absorbent pads if loose liquid was discovered on lids of drums.

Wastes Disposal Location: Cleanup activities not complete at this time. Most likely the one ounce of reported material released will evaporate before contractor arrival. It is expected that little to no waste will be generated from this release.

Agencies Involved:

Updates

Date: 9/12/2013 ***Status:*** Reviewed - No Action Required

Author: Roberts, Kris

Updated Volume:

Notes:

Loose drum bungs. Air release from transport truck. No material on ground according to the report. No follow-up necessary unless response company reports otherwise.